

SPECIFICATION FOR APPROVAL

MODEL : RE200BET-P

PYROELECTRIC INFRARED SENSOR

**CUSTOMER:
APPROVED BY:
DATE:**

TYPE: RE200BET-P

PAGE: 1 /6

CHART:

EDITION: A

SHANGHAI NICERA SENSOR CO.,LTD

TYPE OF SENSOR

GENERAL PURPOSE DUAL ELEMENTS(EMS、LOW VOLTAGE、
STARTTIME FASTER TYPE.)

PHYSICAL CONFIGURATION

- | | |
|------------------------|--------------------------------|
| (1) PACKAGE | TO-5 METAL CAN
SEE FIGURE A |
| (2) SENSITIVE AREA | 2.3×1.0 mm |
| (3) LEAD CONFIGURATION | SEE FIGURE B,C |

ELECTRICAL CHARACTERISTICS (AT 25±5°C)

- | | |
|---------------------------|--|
| (1) CIRCUIT CONFIGURATION | SEE FIGURE D |
| (2) SUPPLY VOLTAGE | 1~15 V DC (Drain-Ground)
(Rs: 470KΩ) |
| (3) OFFSET VOLTAGE | 0.2~1.4 V |
| (4) SIGNAL OUTPUT | Min 3.0 Vp-p
TYP 4.0 Vp-p (Source-Ground)
(BLACK BODY 420K; CHOPPER
FREQUENCY 1Hz: MEASUREMENT
AMP. 0.3~3.0Hz、 72.5db(AT 1Hz))
SEE FIGURE F |
| (5) BALANCE OUTPUT | Max 15% (Source-Ground) (B/Sa+Sb)
(BLACK BODY 420K; CHOPPER
FREQUENCY 1Hz: MEASUREMENT
AMP. 0.3~3.0Hz、 72.5db(AT 1Hz))
SEE FIGURE G |

TYPE: RE200BET-P

PAGE: 2 /6

CHART:

EDITION: A

SHANGHAI NICERA SENSOR CO.,LTD

- A. IN RAPID ENVIRONMENTAL TEMPERATURE CHANGES.
- B. IN STRONG SHOCK OR VIBRATION. CUSTOMERS TO USE FALL PROTECTION, CERAMIC CHIP FRAGILE.
- C. IN A PLACE WHERE THERE ARE OBSTRUCTING MATERIALS (GLASS.FOG.ETC) THROUGH WHICH INFRARED RAYS CANNOT PASS WITHIN DETECTION AREA.
- D. IN FLUID. CORROSIVE GASES AND SEA BREEZE.
- E. CONTINUAL USE IN HIGH HUMIDITY ATMOSPHERE.
- F. EXPOSED TO DIRECT SUN LIGHT OR HEADLIGHTS OF AUTOMOBILES.
- G. EXPOSED TO DIRECT WIND FROM A HEATER OR AIR CONDITIONS.
- H. PRODUCTION PROCESS, NOT THE ACCUMULATION OF STACKED PCB BOARD, THE FILTER IS EASILY DAMAGED.

3. ASSEMBLY RESTRICTIONS/PRECAUTIONS

SOLDERING-----

- A. USE SOLDERING IRONS WHEN SOLDERING.
- B. AVOID KEEPING PINS OF THIS HOT FOR A LONG TIME AS EXCESSIVE HEAT MAY CAUSE DETERIORATION OF ITS QUALITY.(E.G. WITHIN 5 SEC. AT 350°C)
- C. AVOID STATIC ELECTRICITY OR STRONG ELECTROMAGNETIC WAVES. RECOMMENDED TO WEAR A SHIELD RING.

WASHING-----

- A. BE SURE TO WASH OUT ALL FLUX AFTER SOLDERING AS REMAINDER MAY CAUSE MALFUNCTIONS.
- B. USE A BRUSH WHEN WASHING. WASHING WITH AN ULTRASONIC CLEANER MAY CAUSE OPERATIONAL FAILURE.

4. HANDLING AND STORAGE RESTRICTIONS/PRECAUTIONS

TO PREVENT SENSOR MALFUNCTIONS, OPERATIONAL FAILURE. APPEARANCE DAMAGE OR ANY DETERIORATION OF ITS CHARACTERISTICS. DO NOT EXPOSE THIS SENSOR TO THE FOLLOWING OR SIMILAR, HANDLING AND STORAGE CONDITIONS.

- A. VIBRATION FOR A LONG TIME.
- B. STRONG SHOCK.
- C. STATIC ELECTRICITY OR STRONG ELECTROMAGNETIC WAVES.
- D. HIGH TEMPERATURE AND HUMIDITY FOR A LONG TIME.
- E. CORROSIVE GASES OR SEA BREEZE.
- F. DIRTY AND DUSTY ENVIRONMENTS THAT MAY CONTAMINATE THE OPTICAL WINDOWS.

SENSOR TROUBLES RESULTING FROM MISUSE. INAPPROPRIATE HANDLING OR STORAGE ARE NOT THE MANUFACTURER ' S RESPONSIBILITY.

TYPE: RE200BET-P


PAGE: 4 /6

CHART:


EDITION: A

SHANGHAI NICERA SENSOR CO.,LTD


**TOP VIEW
(FIGURE A)**




**SIDE VIEW
(FIGURE B)**



**BASE VIEW
(FIGURE C)**




**CIRCUIT CONFIGURATION
(FIGURE D)**



**MEASUREMENT RECORDER
AMP.**

**FIELD OF VIEW
(FIGURE I)**



TYPE: RE200BET-P

PAGE: 5/6


CHART:

EDITION: A


ASSEMBLY:

SHANGHAI NICERA SENSOR CO.,LTD


**TEST DIAGRAM
(FIGURE E)**




OCCLUDER POSITION



**SIGNAL OUTPUT
(FIGURE F)**



**BALANCE OUTPUT
(FIGURE G)**



**NOISE OUTPUT
(FIGURE H)**

TYPE: RE200BET-P

PAGE: 6/6

CHART:

EDITION: A

ASSEMBLY:

SHANGHAI NICERA SENSOR CO.,LTD